

File E59244  
Project 82NK19442

October 22, 1982

REPORT

on

COMPONENT - RELAY SOCKETS AND ASSEMBLIES

Potter & Brumfield, Div. of  
AMF, Inc.  
Princeton, IN

Copyright © 1982 Underwriters Laboratories Inc.

Underwriters Laboratories Inc. authorizes the above named company to reproduce this Report provided it is reproduced in its entirety.

Underwriters Laboratories Inc. authorizes the above named company to reproduce that portion of this Report consisting of this Cover Page through Page 2.

DESCRIPTION

PRODUCT COVERED:

Relay receptacles, Cat. Nos. 27E043, 27E046, 27E067, 27E305, 27E310,  
\*37E396, 27E397, 27E400, 27E415, 27E419, 27E497, 27E498, 27E499, 27E797, 27E798,  
27E800 27E801 and 27E818.