File E59244 Project 80NK17054

January 16, 1981

REPORT

on

COMPONENT - RELAY SOCKETS AND ASSEMBLIES

Potter & Brumfield Div. of AMF, Inc. Princeton, Indiana

Copyright © 1981 Underwriters Laboratories Inc.

Underwriters Laboratories Inc. authorizes the above named company to reproduce this Report provided it is reproduced in its entirety.

File E59244 Vol. 1 Sec. 2 Page 1 Issued: 1981-01-16 and Report Revised: 2006-06-27

DESCRIPTION

PRODUCT COVERED:

Component - relay socket assembly, Cat. Nos. 27E460, 27E461, 27E462, 27E464 and 27E867.

GENERAL:

Rating - For use in Class 2 circuits or Limited Voltage Limited Current circuits only.