

CERTIFICATE OF COMPLIANCE

Certificate Number 20190731-E315442
Report Reference E315442-20160318
Issue Date 2019-JULY-31

Issued to: TYCO ELECTRONICS CORP
2901 FULLING MILL RD
MIDDLETOWN, PA 17057 USA

This certificate confirms that representative samples of CONNECTOR HOUSINGS - COMPONENT
See Addendum Page

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL Subject 2441 - Outline of Investigation for Component-Connector Housings

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE


Certificate Number 20190731-E315442
Report Reference E315442-20160318
Issue Date 2019-JULY-31

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Models 1-2292404-8, 2-2292405-0, 2296205-2, 2296205-4, 2296205-6, 2296205-8, 1-2296205-0, 1-2296205-2, 1-2296205-4, 1-2296205-6, 1-2296205-8, 2-2296205-0, 2-2296205-2, 2-2296205-4, 2296206-2, 2296206-4, 2296206-6, 2296206-8, 1-2296206-0, 1-2296206-2, 1-2296206-4, 1-2296206-6, 1-2296206-8, 2-2296206-0, 2-2296206-2, 2-2296206-4, 2296207-2, 2296207-4, 2296207-6, 2296207-8, 1-2296207-0, 1-2296207-2, 1-2296207-4, 1-2296207-6, 1-2296207-8, 2-2296207-0, 2-2296207-2, 2-2296207-4, 1969597-2, 1969597-4, 1969597-6, 1969597-8, 1-1969597-0, 1-1969597-2, 1-1969597-4, 1-1969597-6, 1-1969597-8, 2-1969597-2, 2-1969597-4, 1969598-2, 1969598-4, 1969598-8, 1-1969598-0, 1-1969598-4, 1-1969598-8, 2-1969598-4, 1-1969599-0, 1-1969599-2, 1-1969599-4, 1-1969599-6, 1-1969599-8, 2-1969599-4, 1969603-2, 1969603-4, 1969603-6, 1969603-8, 1-1969603-0, 1-1969603-2, 1-1969603-4, 1-1969603-6, 1-1969603-8, 2-1969603-0, 2-1969603-2, 2-1969603-4, 1969612-4, 1-1969612-4, 1-1969612-6, 1-1969612-8, 2-1969612-0, 2-1969612-4, 1969613-2, 1969613-8, 1-1969613-4, 1-1969613-6, 1-1969613-8, 2-1969613-2, 2-1969613-4, 1-1969614-4, 1-1969614-6, 1-1969614-8, 2-1969614-4, 1969614-2, y-2834206-x (c)(d), y-2834219-x (c)(d), y-2834224-x (c)(d), y-2834225-x (c)(d), y-2834295-x (c)(d), y-2834296-x (c)(d), y-2834297-x (c)(d), y-2834298-x (c)(d), y-2834266-x (c)(d), 1969613-4, 1969613-6, 1-1969613-0, 1-1969613-2, 1969612-2, 1969612-6, 1969612-8, 1-1969612-0, 1-1969612-2, 2-1969612-2, 1969598-2, 1969598-4, 1969598-6, 1969598-8, 1-1969598-0, 1-1969598-2, 1-1969598-4, 1-1969598-6, 1-1969598-8, 2-1969598-0, 2-1969598-2, 2-1969598-4, 1969599-2, 1969599-4, 1969599-6, 1969599-8, 1-1969599-0, 1-1969599-2, 1-1969599-4, 1-1969599-6, 1-1969599-8, 2-1969599-0, 2-1969599-2, 2-1969599-4, 1969613-2, 1969613-4, 1969613-6, 1969613-8, 1-1969613-0, 1-1969613-2, 1-1969613-4, 1-1969613-6, 1-1969613-8, 2-1969613-0, 2-1969613-2, 2-1969613-4, 1969614-2, 1969614-4, 1969614-6, 1969614-8, 1-1969614-0, 1-1969614-2, 1-1969614-4, 1-1969614-6, 1-1969614-8, 2-1969614-0, 2-1969614-2, 2-1969614-4

(c) - Where y and x can be any digit 0-9. If y is 0, blank will be used

(d) - Where y and x combined as yx matches the number represented in basic model XX



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

